

Service Bulletin No. RP20050927 Subject: Rewiring Low Engine Oil Warning Buzzer Model: MVH-406DSY & MVH-306DS2 Product Group: Reversible Vibratory Plates Date: September 27, 2005

# SERVICE BULLETIN

# Group: RP

**X** Mandatory

Information

**Recommended Change** 

## **Series/Parts Affected:**

#### <u>Machines Affected:</u> <u>MVH-406DSY S/N's N1001 to N1003 and S/N's N1007 to N1011</u> <u>MVH-306DS2 S/N's N2602 to N2611 and S/N's 2684 to 2713</u>

### SERVICE INFORMATION

It has been determined that the above referenced units have the low oil warning buzzer incorrectly wired.

These units currently have the warning buzzer wired directly to 12V DC at all times. When battery is installed, the buzzer will sound without the engine running. In order to ensure low oil warning system is functioning properly, perform the following procedure.

### INSTRUCTIONS





- <text>
  - 6. Reconnect the connector and return fuse back in place.

### WARRANTY INFORMATION

#### Campaign Reference No. 20050927

Please contact Chris Fairchild or George Manrique @ 1-800-421-1244 for warranty claim number and warranty form.

#### Labor Allowance: Flat Rate to install – 6 minutes