



Service Bulletin No. LT20060918
Subject: Light Tower Ballast Wiring
Models: MB400B
Product Group: Light Tower
Date: September 18, 2006

SERVICE BULLETIN

Group: LT

Mandatory

Information

Recommended Change

Series/Parts Affected:

Machines Affected:

ModelSerial number Range

MB400B.....ALL

SERVICE INFORMATION

CAUSE: The above referenced serial number balloon light towers may experience the following:

Unknown overload conditions exist within the balloon light tower ballast which has caused the wiring on and around the ON/OFF switch to burn the insulation and expose the bare copper wiring. These conditions make use of the light tower unsafe and create the possibility of fire or severe electrical shock.

SOLUTION:

STOP! using balloon light tower (ballast) until a replacement ballast is available.

DANGEROUS! electrical conditions (shock/fire) exist if you continue to use the balloon light tower ballast. ***These conditions could cause damage to the equipment and severe bodily harm even death!***