



Service Bulletin No. LT20060825
Subject: Light Tower Ballast Wiring
Models: MB1000
Product Group: Light Tower
Date: August 25, 2006

SERVICE BULLETIN

Group: LT

Mandatory

Information

Recommended Change

Series/Parts Affected:

Machines Affected:

Model Serial number Range

MB1000ALL

SERVICE INFORMATION

CAUSE: The above referenced serial number balloon light towers may experience the following:

Unknown overload conditions exists within the balloon light tower ballast which has caused the wiring on and around the ON/OFF switch to burn the insulation and expose the bare copper wiring. These conditions make use of the light tower unsafe and create the possibility of fire or severe electrical shock.

SOLUTION:

STOP! using balloon light tower (ballast) until a replacement ballast is available.

DANGEROUS! electrical conditions (shock/fire) exists if you continue to use the balloon light tower ballast. ***These conditions could cause damage to the equipment and severe bodily harm even death!***